SENSORS OF AIR-TEMPERATURE





BEA resistance type

Description:

Resistance air-temperature sensor with connection head and compression fitting, (perforated or closed design). *Temperature*: -200...+600°C, -50...+400°C


Accessories on request

Perforated design

Closed design

Closed design

Ordering code:



Naturally, we can differ from the above construction.